



Snipe Class International Racing Association Change Rule - Proposal Form

RPF - 0120260226

Date of submission: 2026-02-20

Code: 26 - 002

From SCIRA Board Technical Committee National Secretary 5 Fleet Captains

Email sciraexecutivedirector@gmail.com

Summary To fix the daggerboard trunk to the hull

Affects

Constitution By-Laws Class Rules Deed of Gift Rules of Conduct NoR or SI Template

OBJECTIVE

Add the requirement for the daggerboard trunk to be fixed to the hull

CURRENT RULE

C.8.4.a) 9)
Any seals on the daggerboard case may be used only at the top of the daggerboard case.

PROPOSAL RULE

C.8.4.a) 9)
Any seals on the daggerboard case may be used only at the top of the daggerboard case. The daggerboard trunk shall be fixed to the hull with no less than 12 screws located as follows:
Top of daggerboard case on port: 3 screws
Top of daggerboard case on starboard: 3 screws
Bottom of daggerboard case on port to the floor of the deck: 3 screws
Bottom of daggerboard case on port to the floor of the deck: 3 screws

REASONS

Some boats are removing the screws from the daggerboard trunk (specially at the top of the daggerboard trunk) to permit side movements of the daggerboard.